

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number: [1301790142](#)
Status: **Active**
Overview: [Aero-Motive Repair Parts and Accessories](#)
Description: Assembly Spring and Cable Drum for 5FLR Series

Documents:
[RoHS Certificate of Compliance \(PDF\)](#)

General

Product Family	Tool Supports
Series	130179
Cable Length	N/A
Duty	N/A
Overview	Aero-Motive Repair Parts and Accessories
Product Name	Aero-Motive
Type	Replacement Part, Spring Assembly
UPC	78678808062
Woodhead	Yes

Physical

Cable Diameter	N/A
Cable Movement	N/A
Drum Lock	None
Mounting Style	N/A
Packaging Type	Carton
Travel Distance	N/A
Weight Range	N/A
Wire/Cable Type	N/A

Material Info

Engineering Number	9883
--------------------	------



Series image - Reference only

EU ELV

Not Reviewed

EU RoHS

Not Reviewed

REACH SVHC

Not Reviewed

Halogen-Free

Status

Not Reviewed

Need more information on product environmental compliance?

Email productcompliance@molex.com
Please visit the [Contact Us](#) section for any non-product compliance questions.

China ROHS	Not Reviewed
ELV	Not Reviewed
RoHS Phthalates	Not Reviewed

Search Parts in this Series
[130179 Series](#)

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION