INSTALLATION INSTRUCTIONS FOR L957 PENDANT ADAPTER

FOR USE WITH HALO TRACK SYSTEMS ONLY IMPORTANT SAFETY INSTRUCTIONS

MAX. FIXTURE WEIGHT 35 POUNDS

INSTALLATION


STEP 1. Remove side cover. Install link from fixture chain on loop.

STEP 2. Insert 2 wires plus bare copper ground wire from chain hung fixture through bottom opening and out through side of L957 adapter.

STEP3. Bring 3 wires from L957 adapter out through side access (black, white, and green or bare).

STEP 4. With wire nuts, connect the black adapter wire to the "solid" color or plain wire from fixture. Connect the white adapter wire to the "identified" white striped or ribbed wire from the fixture - see drawing. Connect the green or bare adapter wire to the bare wire from fixture.

STEP 5. Securely fasten all wire nuts and push wires back in box. Screw side cover in place.



SAVE THESE INSTRUCTIONS

