

WIRE MANAGEMENT

Self-Adhesive Label

Lockout/Tagout
VL, DSS Series

CAUTION: In Accordance with OSHA Standard 1910.147, All Equipment, Machines and Processes Shall Be Locked Out Prior to Servicing. Lockout Procedures are Posted in the Main Operating Area and/or by the Main Energy Source of Each Machine. If You Have any Questions About the Lockout Procedures, Please See Your Supervisor or the Safety Director. This Standard Will Be Strictly Enforced.

FEATURES

- Self-adhesive labels are sub-surface printed polyester labels.
- Rigid signs are available in either polycarbonate or polyester material.



CAT. NO.	FIG. NO.	LEGEND	SIZE (IN.)	STD. CTN. QTY.
VL-7	1	Warning Potential Arc-Flash Hazards Exist While Working on this Energized Equipment.	2 1/4 x 4 1/2	25
VL-8	2	Warning Potential Arc-Flash Hazards Exist While Working on this Energized Equipment.	4x6	25
DSS-5	3	High Voltage.	10 x 14	25
DSS-6	4	High Voltage Keep Out.	10 x 14	25